Sma photovoltaic inverter error code 34

Why is my SMA inverter NOT working?

The cause must be determined by the SMA Service Line. Contact the SMA Service Line. The communication version of an inverter is not supported or the device combination is invalid. Contact the SMA Service Line and request the latest firmware package,if necessary. Communication with one or several inverters is no longer possible.

What do error codes mean on a solar inverter?

These error codes indicate specific problemsor conditions that may arise with the inverter. It's important to note that the specific meaning and troubleshooting steps for each error code can vary depending on the inverter model and firmware version. It's always recommended to consult the user manual or contact Future Solar WA solar experts.

Are SMA Solar inverters reliable?

SMA Solar Technology,a German-based company founded in 1981,is a leading global distributor of solar power solutions. Their inverters are highly regarded for reliability,making them popular in the Australian market. This guide will explore the most common error codes of SMA inverters,their causes,and recommended corrective measures.

Is SMA Solar Technology AG liable for information provided in the OSC?

SMA Solar Technology AG accepts no liabilityfor the content or accuracy of the information provided in the OSC. SMA Online Service Center Terms and Conditions apply accordingly. All work on the inverter and the cabling of the photovoltaic array must be carried out by electrically qualified persons.

What if my SMA grid guard code is incorrect?

Contact the Service. The SMA Grid Guard code entered is incorrect. The operating parameters are still protected and cannot be changed. Enter the correct SMA Grid Guard code. Changes to the grid parameters are now blocked. In order to be able to make changes to the grid parameters,from now on you must log in using the SMA Grid Guard code.

Why is my SMA backup unit controller not receiving data?

Ensure that the cable requirements of the communication cable for the communication between the SMA Backup Unit Controller and the inverter have been met. Retry update. If this message is displayed again, contact the Service. The inverter is not receiving any data from the energy meter.

PV system operators and installers receive fast support when they need it via our new SMA Online Service Center. You can use this to contact our Service team, look at the status of your service cases and access ...

SMA Sunny Boy US inverters are now available with integrated Arc Fault Circuit Interrupter (AFCI)

functionality. ... Integrating AFCI functionality within the PV system inverter eliminates the cost and effort of installing additional arc-fault ...

Web: https://www.nowoczesna-promocja.edu.pl